

Attorney's Docket 0040258-0274025
Client Reference: T2SK-02S0853-1



FW CofC

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re PATENT APPLICATION of:
OHMI et al.

Confirmation Number: 9698

Application No.: 09/678,741

Group Art Unit: 1763

Filed: October 4, 2000

Examiner: Anna M. Crowell

For: PLASMA PROCESSING APPARATUS

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER 37 U.S.C. §254 AND PURSUANT TO 37 C.F.R. §1.322
(PTO's Mistake)

Commissioner for Patents
Post Office Box 1450
Alexandria, VA 22313-1450

Sir:


It is respectfully requested that a Certificate of Correction be issued in the above-identified patent to correct an error found, in the title of the invention, made by the U.S. Patent and Trademark Office (USPTO).

Attached are two properly completed Certificate of Correction Forms PTO-1050 showing the needed correction. It is requested that these forms be certified by the Commissioner, with one form being returned to the undersigned attorney.

Because the error is the fault of the USPTO, no fee is required. However, should a fee be required to effect this Request, the Commissioner is hereby authorized to charge the required fee to our Deposit Account No. 03-3975, Order No. 008312-0302452.

Respectfully submitted,

PILLSBURY WINTHROP LLP


Jeffrey D. Karceski
Reg. No.: 35914
Tel. No.: (703) 905-2110
Fax No.: (703) 905-2500

March 25, 2005

P.O. BOX 10500
McLean, Virginia 22102
(703) 905-2000
Customer Number 00909

APR 20 2005

BEST AVAILABLE COPY

PTO/SB/44 (04-04)

Approved for use through 04/30/2007. OMB 0851-0033

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

PATENT NO : 6830652

DATED : December 14, 2004

INVENTOR(S) : TADAHIRO OHMI, ET AL

It is certified that error appears in the above-identified patent and that said Letters Patent
is hereby corrected as shown below:

On title page, item 54 Title of Invention
replace "Microwave Plasma Processing Apparatus"
with --Plasma Processing Apparatus--.

MAILING ADDRESS OF SENDER:
PILLSBURY WINTHROP LLP
P.O. Box 10500
McLean, VA 22102

PATENT NO. 6830652

No. of additional copies

⇒ 3

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

APR 20 2005